

FIG 1a




FIG 1b




FIG 1c




FIG 1e




FIG 1f




FIG 1g




FIG 2a




FIG 2c




FIG 2b




FIG 2d




FIG 2e




FIG 2f




FIG 2g




FIG 2h

ETCH AND POLISH




FIG 3a




FIG 3b




FIG 3c




FIG 3d




FIG 3e




FIG 3f




FIG 3g




FIG 3h




FIG 3i




FIG 3j